

The house, side by side.

95 reference photographs paired with views of the rebuilt 3D house.

September 20, 2026 | 6618 Nahal Drive, Frederick, Maryland

REFERENCE PHOTOGRAPH



REBUILT MODEL



Wall and door geometry uses the supplied floor plan and Polycam scans. Photographs guide finishes, colors and built-in details. Each comparison includes a link to its saved browser view for inspection.

Front-left aerial

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Hip/gable intersections; chimney; garage doors; roof shingle scale; brick and trim.

Open this view in the walkthrough

Reference: 001-6618-Nahal-Dr.jpg

Front aerial

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

All front window shapes and bay; façade proportions; entrance arch; garage attic arch.

Open this view in the walkthrough

Reference: 002-6618-Nahal-Dr.jpg

Rear aerial

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Main roof; porch; detached garage; pool L-shape; fences and hardscape.

Open this view in the walkthrough

Reference: 003-6618-Nahal-Dr.jpg

Front elevation

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Three study arches, large foyer arch, garage attic arch; two-story bay and round vent.

Open this view in the walkthrough

Reference: 004-6618-Nahal-Dr.jpg

Rear-left aerial

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Detached garage three-door side; family cross-gable; deck; pool and trees.

Open this view in the walkthrough

Reference: 005-6618-Nahal-Dr.jpg

Pool chaise viewpoint

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Pool surround and coping; detached garage pool wall; black fence. Loose chairs are staging.

Open this view in the walkthrough

Reference: 006-6618-Nahal-Dr.jpg

Pool toward house

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Pool diving board, water and coping; rear elevations and detached garage.

Open this view in the walkthrough

Reference: 007-6618-Nahal-Dr.jpg

Wide front-left aerial

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Driveway footprint, roof silhouettes, trees and overall placement.

Open this view in the walkthrough

Reference: 008-6618-Nahal-Dr.jpg

Driveway approach

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Driveway curve, attached garage front gable, grass and tree positions.

Open this view in the walkthrough

Reference: 009-6618-Nahal-Dr.jpg

Address stone and front garden

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Address marker, planting bed, asphalt and front elevation.

Open this view in the walkthrough

Reference: 010-6618-Nahal-Dr.jpg

Wide front lawn

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Front lawn grade, house windows, shrubs and mature trees.

Open this view in the walkthrough

Reference: 011-6618-Nahal-Dr.jpg

Front from right

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Bay shape, gables, foyer arch, grass and trees.

Open this view in the walkthrough

Reference: 012-6618-Nahal-Dr.jpg

Attached garage side

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Two garage doors, electric meter, coach lights, fireplace chimney and drive.

Open this view in the walkthrough

Reference: 013-6618-Nahal-Dr.jpg

Detached garage approach

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Three sectional doors; front pair of shuttered windows; circular gable vent; eaves.

Open this view in the walkthrough

Reference: 014-6618-Nahal-Dr.jpg

Front entrance detail

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Black door, sidelights, pilasters, transom, exterior sconces and brick steps.

Open this view in the walkthrough

Reference: 015-6618-Nahal-Dr.jpg

Inside front doorway

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Entrance leaf and sidelights; black exterior versus white interior door finish.

Open this view in the walkthrough

Reference: 016-6618-Nahal-Dr.jpg

Foyer toward front door

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Two-story void, oak balustrade, closet door and front entry glazing.

Open this view in the walkthrough

Reference: 017-6618-Nahal-Dr.jpg

Foyer staircase

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Winder layout, tread heights, oak balusters and living-room opening.

Open this view in the walkthrough

Reference: 018-6618-Nahal-Dr.jpg

Stair base detail

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Curved starting handrail, newels, risers and basement stair door.

Open this view in the walkthrough

Reference: 019-6618-Nahal-Dr.jpg

Stair winders

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Turn geometry; top landing; oak rail and turned balusters.

Open this view in the walkthrough

Reference: 020-6618-Nahal-Dr.jpg

Study full room

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Three arched windows; blue paint; oak floor and three-bay library wall; fan.

Open this view in the walkthrough


Reference: 021-6618-Nahal-Dr.jpg

Study library detail

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Arched oak shelf bays, blue center back panel, six lower cabinet doors and moldings.

[Open this view in the walkthrough](#)

Reference: 022-6618-Nahal-Dr.jpg

Foyer reverse view

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Entry arch, stair profile, room openings, oak flooring and white trim.

Open this view in the walkthrough

Reference: 023-6618-Nahal-Dr.jpg

Living room side windows

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Two narrow side windows; gray carpet; fan and crown.

[Open this view in the walkthrough](#)

Reference: 024-6618-Nahal-Dr.jpg

Living room bay

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Three-sided bay, lower glazing, window drapes, carpet and fan.

Open this view in the walkthrough

Reference: 025-6618-Nahal-Dr.jpg

Dining room toward side window

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Gray walls and teal east accent wall; white chair rail, gray carpet and wood-and-glass pendant.

Open this view in the walkthrough

Reference: 026-6618-Nahal-Dr.jpg

Dining toward living room

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Rear and side windows, teal wall sections, chair rail and wide living opening.

Open this view in the walkthrough

Reference: 027-6618-Nahal-Dr.jpg

Powder room

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Teal walls, pedestel basin, oval mirror, three-light sconce and toilet.

Open this view in the walkthrough

Reference: 028-6618-Nahal-Dr.jpg

Kitchen front-on

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Cabinet cathedral profiles, black pulls, island shape/color and three-part sink window.

Open this view in the walkthrough

Reference: 029-6618-Nahal-Dr.jpg

Kitchen fridge galley

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Fridge and wine rack, island clearance, hutch and family-room sightline.

Open this view in the walkthrough

Reference: 030-6618-Nahal-Dr.jpg

Kitchen hutch close-up

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Two glazed upper doors; center paired doors; scalloped valance; drawer pedestals; subway tile.

Open this view in the walkthrough

Reference: 031-6618-Nahal-Dr.jpg

Kitchen from breakfast nook

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Island rounded overhang, sink run, microwave and wall oven, soffits, pendant pair.

[Open this view in the walkthrough](#)

Reference: 032-6618-Nahal-Dr.jpg

Kitchen toward fridge and hutch

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Blue island raised panels and angled end, fridge, wine rack and hutch.

[Open this view in the walkthrough](#)

Reference: 033-6618-Nahal-Dr.jpg

Kitchen backsplash corner

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Glazed gray subway tile, thin grout, corner display cabinet and warm-gray counter.

[Open this view in the walkthrough](#)

Reference: 034-6618-Nahal-Dr.jpg

Blue island fronts

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Drawer count, paired doors, angled end door, black handles and blue finish.

Open this view in the walkthrough

Reference: 035-6618-Nahal-Dr.jpg

Refrigerator interior

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Appliance interior shelves and door bins; drawer proportions.

Open this view in the walkthrough

Reference: 036-6618-Nahal-Dr.jpg

Kitchen island toward family room

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Electric downdraft cooktop, stone texture, pendant positions, breakfast opening and fireplace.

Open this view in the walkthrough

Reference: 037-6618-Nahal-Dr.jpg

Kitchen sink detail

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Double sink, dark gooseneck faucet, dishwasher, three-part window and subway tile.

Open this view in the walkthrough

Reference: 038-6618-Nahal-Dr.jpg

Breakfast and family room

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Porch doors and transom, breakfast chandelier, family half-wall and vault.

[Open this view in the walkthrough](#)

Reference: 039-6618-Nahal-Dr.jpg

Family to kitchen opening

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Wide opening and half-height end wall; floor transition; ring chandelier.

Open this view in the walkthrough

Reference: 040-6618-Nahal-Dr.jpg

Breakfast nook reverse

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Porch access, dining nook, kitchen cabinets and island side.

Open this view in the walkthrough

Reference: 041-6618-Nahal-Dr.jpg

Screened porch

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Angled porch corner; dark mesh framing; chevron decking; wicker fan.

Open this view in the walkthrough

Reference: 042-6618-Nahal-Dr.jpg

Screened porch duplicate angle

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE


Near-duplicate of 042; included separately for complete photo coverage.

[Open this view in the walkthrough](#)

Reference: 043-6618-Nahal-Dr.jpg

Porch toward house

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Brick house wall, glazed double entry, angled decking and screen door.

Open this view in the walkthrough

Reference: 044-6618-Nahal-Dr.jpg

Family vaulted room

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Actual sloping transom glass, brick fireplace arch, white built-ins and vaulted ceiling.

[Open this view in the walkthrough](#)

Reference: 045-6618-Nahal-Dr.jpg

Family room lit staging

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Warm lighting variant; shelf profiles, triangular transoms, French doors and flooring.

[Open this view in the walkthrough](#)

Reference: 046-6618-Nahal-Dr.jpg

Family room second wide

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Vault, chimney, ceiling fan and full-height glazing; staging furniture excluded.

Open this view in the walkthrough

Reference: 047-6618-Nahal-Dr.jpg

Family room side angle

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Fireplace depth, side glazing, hearth outline and built-in millwork.

Open this view in the walkthrough

Reference: 048-6618-Nahal-Dr.jpg

Fireplace and built-ins

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Segmental brick arch, recessed firebox, oak mantel, chamfered hearth and cabinet doors.

Open this view in the walkthrough

Reference: 049-6618-Nahal-Dr.jpg

Family toward kitchen

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

French door bank, transoms, breakfast opening, fan and wood direction.

Open this view in the walkthrough

Reference: 050-6618-Nahal-Dr.jpg

Laundry cabinetry

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Upper white cathedral cabinets, tall pantry, dryer and top-load washer.

Open this view in the walkthrough

Reference: 051-6618-Nahal-Dr.jpg

Attached garage

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Two overhead doors, tracks/openers, front windows and original concrete floor.

Open this view in the walkthrough

Reference: 052-6618-Nahal-Dr.jpg

Primary bedroom

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Two ceiling fans, front double window, beige carpet and bath/closet doors.

Open this view in the walkthrough

Reference: 053-6618-Nahal-Dr.jpg

Primary bedroom wide

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Window proportions, room depth, two fans, carpet and paint.

Open this view in the walkthrough

Reference: 054-6618-Nahal-Dr.jpg

Primary bedroom reverse

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Bathroom and hall entries, closet door, ceiling fans and paint.

Open this view in the walkthrough

Reference: 055-6618-Nahal-Dr.jpg

Primary bathroom entrance

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Stepped tub deck, shaped window, oak vanity, stone tile and recessed lights.

Open this view in the walkthrough

Reference: 056-6618-Nahal-Dr.jpg

Primary shower detail

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Large marble-look porcelain, grout, shower glass, black plumbing and niches.

Open this view in the walkthrough

Reference: 057-6618-Nahal-Dr.jpg

Primary double vanity

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Oak joinery, twin arched mirrors, two three-light fittings and white counter.

[Open this view in the walkthrough](#)

Reference: 058-6618-Nahal-Dr.jpg

Primary tub and window

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Stepped arched transom, side casements, tub profile, tiled deck and step.

Open this view in the walkthrough

Reference: 059-6618-Nahal-Dr.jpg

Walk-in closet

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Two adjoining measured ceiling pitches; low/tall organizers, central island and fluorescent fitting.

Open this view in the walkthrough

Reference: 060-6618-Nahal-Dr.jpg

Upper landing

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Open-to-below boundary, newels, bedroom/bath doors and foyer window shape.

Open this view in the walkthrough

Reference: 061-6618-Nahal-Dr.jpg

Upper stair toward entry

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Two-story entry, upper window, chandelier, balustrade curvature and landing.

Open this view in the walkthrough

Reference: 062-6618-Nahal-Dr.jpg

Bedroom two toward window

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Gray walls, carpet, rectangular window and ceiling fan.

Open this view in the walkthrough

Reference: 063-6618-Nahal-Dr.jpg

Bedroom two closet doors

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Paired closet doors, attic hatch, fan, door casing and baseboards.

Open this view in the walkthrough

Reference: 064-6618-Nahal-Dr.jpg

Blue bedroom

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Blue paint, wood accent wall, white closet doors and dark wood fan.

Open this view in the walkthrough

Reference: 065-6618-Nahal-Dr.jpg

Blue bedroom reverse

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Plank accent wall, window grille and door placement.

Open this view in the walkthrough

Reference: 066-6618-Nahal-Dr.jpg

Hall bathroom

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Wood vanity and floor, white counter, framed mirror, triple light and alcove bath.

Open this view in the walkthrough

Reference: 067-6618-Nahal-Dr.jpg

Front bedroom

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Bay window, teal paneled accent wall, carpet and fan.

Open this view in the walkthrough

Reference: 068-6618-Nahal-Dr.jpg

Front bedroom accent wall

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Teal board-and-batten detail; closet doors; right-side window and fan.

[Open this view in the walkthrough](#)

Reference: 069-6618-Nahal-Dr.jpg

Basement recreation window

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Gray carpet, low soffits, rectangular double window, post and rear walkout door.

[Open this view in the walkthrough](#)

Reference: 070-6618-Nahal-Dr.jpg

Basement toward walkout

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Rear exterior door, high narrow window, ceiling beam, column and baseboard heating.

[Open this view in the walkthrough](#)

Reference: 071-6618-Nahal-Dr.jpg

Basement gym

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Wood floor and accent wall, recessed lights and room doors. Exercise equipment is loose furnishing.

Open this view in the walkthrough

Reference: 072-6618-Nahal-Dr.jpg

Basement gym reverse

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Gym doors, window recess, wood flooring and ceiling light positions.

Open this view in the walkthrough

Reference: 073-6618-Nahal-Dr.jpg

Basement bath doorway

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Aqua paint, white vanity, taupe counter, toilet and distressed plank tile.

[Open this view in the walkthrough](#)

Reference: 074-6618-Nahal-Dr.jpg

Basement vanity

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Vanity joinery, wood mirror, dark faucet, towel ring and aqua paint.

Open this view in the walkthrough

Reference: 075-6618-Nahal-Dr.jpg

Basement shower left

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Distressed cream plank tile, pebble mosaic, bronze fittings and corner shelves.

Open this view in the walkthrough

Reference: 076-6618-Nahal-Dr.jpg

Basement shower right

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Pebble feature wall versus distressed horizontal tiles; shower head and shelves.

[Open this view in the walkthrough](#)

Reference: 077-6618-Nahal-Dr.jpg

Utility water heater

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Gray water heater, blue pressure tank, filter vessels, utility sink, brine tank and copper pipes.

Open this view in the walkthrough

Reference: 078-6618-Nahal-Dr.jpg

Utility water-treatment tanks

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Two pale treatment tanks, blue pressure vessel, water heater, exposed joists and blockwork.

[Open this view in the walkthrough](#)

Reference: 079-6618-Nahal-Dr.jpg

Utility room length

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Unfinished joists/insulation, concrete block walls, narrow circulation and plant at far end.

Open this view in the walkthrough

Reference: 080-6618-Nahal-Dr.jpg

Rear firepit patio

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Gravel patio outline, edging, paving and black pool fence.

Open this view in the walkthrough

Reference: 081-6618-Nahal-Dr.jpg

Deck toward detached garage

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Garage pair of shuttered windows and round vent; composite deck and fascia.

[Open this view in the walkthrough](#)


Reference: 082-6618-Nahal-Dr.jpg

Rear left elevation

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Chimney, porch, deck, three upstairs rear windows and lawn grade.

Open this view in the walkthrough

Reference: 083-6618-Nahal-Dr.jpg

Rear elevation

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Screened porch, basement stair enclosure, rear window patterns, deck and planting beds.

Open this view in the walkthrough

Reference: 084-6618-Nahal-Dr.jpg

Pool from garage end

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

L-shaped pool, coping, handrails, fence and woodland edge.

Open this view in the walkthrough

Reference: 085-6618-Nahal-Dr.jpg

Pool toward house right

REFERENCE PHOTOGRAPH



COMPARE

Water reflections, pool shape, fence and brick rear façade.

Open this view in the walkthrough

REBUILT MODEL




Reference: 086-6618-Nahal-Dr.jpg

Pool toward garage

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Detached garage pool elevation, coping steps and foliage.

Open this view in the walkthrough

Reference: 087-6618-Nahal-Dr.jpg

Diving-board end

REFERENCE PHOTOGRAPH



COMPARE

Diving board position, waterline tile, pool width and garage behind.

Open this view in the walkthrough

REBUILT MODEL




Reference: 088-6618-Nahal-Dr.jpg

Rear right corner

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Side/rear windows at all levels, twin HVAC condensers, downspouts and patio.

Open this view in the walkthrough

Reference: 089-6618-Nahal-Dr.jpg

Detached garage interior

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Three garage doors, overhead hardware, attic access, lights and concrete.

Open this view in the walkthrough

Reference: 090-6618-Nahal-Dr.jpg

Detached garage workshop wall

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Wall-mounted wire shelves, wood work shelf, suspended unit heater, outlets and concrete slab.

[Open this view in the walkthrough](#)

Reference: 091-6618-Nahal-Dr.jpg

Treehouse stairs

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Raised timber playhouse and stair handrails; tree positions and evergreen branches.

[Open this view in the walkthrough](#)

Reference: 092-6618-Nahal-Dr.jpg

Treehouse through branches

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Occluding evergreen foliage; playhouse silhouette and trunk spacing.

Open this view in the walkthrough

Reference: 093-6618-Nahal-Dr.jpg

Treehouse and slide

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Deck supports, guardrails, stairs and green curved slide.

Open this view in the walkthrough

Reference: 094-6618-Nahal-Dr.jpg

Garage wildlife viewpoint

REFERENCE PHOTOGRAPH



REBUILT MODEL



COMPARE

Garage brick, lighting and nearby lawn. Wildlife is not architectural geometry.

Open this view in the walkthrough

Reference: 095-6618-Nahal-Dr.jpg